Revision D

Connectors

for HELIAX® FSJ1-50A Coaxial Cable





Description

These connectors are designed for flaring of the outer conductor and soldering of the inner connector to the inner conductor of the coaxial cable.

Tools and Materials Required for Assembly


Knife
Flat file
Wire brush
Silicone grease (supplied)
Spacing gauge (supplied)
Damp cloth
Garnet cloth, 240
grit or finer


Wrenches: 9/16", 11/16", and 13/16" (hex coupling nut)
Fine-toothed hacksaw or jeweler's saw
Soldering iron, min. 150 W:
a resistance-type iron is recommended when soldering in low-temperature environments
Solder, 63/37 RMA flux core


Notice


The installation, maintenance, or removal of antenna systems requires qualified, experienced personnel. Andrew installation instructions have been written for such personnel. Antenna systems should be inspected once a year by qualified personnel to verify proper installation, maintenance, and condition of equipment.


Andrew disclaims any liability or responsibility for the results of improper or unsafe installation practices.

















	50		表一 有毒有害物质或元素名称及含量标识格式					
			有毒有害物质或元素					
部件名称	(Part Name)	铅 (Pb)	汞 (Hg)	镉 (Cd)	六价铬 (Cr6+)	多溴联苯 (PBB)	多溴二苯醚 (PBDE)	
連接器	(Connector if attached)	Χ	0	0	0	0	0	

O: 表示有毒有害物质在该部件所有的均质材料中的含量均在SJ/T 11363-2006规定的限量要求以下.

X: 表示该有毒有害物质至少在该部件的某一均质材料中的含量超出SJ/T 11363-2006规定的限量要求



Other Europe: +44 1592 782612